REPÚBLICA DE PANAMÁ
AUTORIDAD AERONÁUTICA CIVIL
DEPARTAMENTO INFORMACIÓN AERONÁUTICA
Sección de Publicaciones Aeronáuticas

Direcciones:
AFS: MPLBYOYX
Comercial: AEROCIVIL Panamá
Tel.: (507) 520-1595 / 1596 / 1594
Fax: (507) NIL
e.mail: aispanama@aeronautica.gob.pa

Apartados 0816-03073 ó
0816-03187
Zona 5, Panamá

ó

Apartado 0843-02086
Balboa, Ancón

SUP

A 20/26

01- Octubre- 2026

AD

A-20/26 MARCOS A. GELABERT INTL AP (MPMG)

Resalto en calle de rodaje

A partir del **1 DE OCTUBRE DE 2026**, hasta el **1 DE OCTUBRE DE 2027**, la calle de rodaje F mantiene un resalto a 473M al sur de la calle de rodaje D localizado en la siguiente coordenadas 085759.48N 0793329.59W.
Tomar precauciones.

REF AIP AD 2.2-6 (30 JUN 2018)
REF AIP AD 2.2-45 (30 SEP 2019)

REPUBLIC OF PANAMÁ
CIVIL AVIATION AUTHORITY
AERONAUTICAL INFORMATION DEPARTMENT
Aeronautical Publications Section

Address: P.O. Box 0816-03073 ó 0816-03187
AFS: MPLBYOYX
Commercial: AEROCIVIL Panamá Zone 5, Panamá
Tel.: (507) 520-1595 / 1596 / 1594 ó
Fax: (507) NIL P.O. Box 0843-02086
e.mail: aispanama@aeronautica.gob.pa Balboa, Ancón

SUP

A20/26

October 1°, 2026

AD

A-20/26 MARCOS A. GELABERT INTL AP (MPMG)
Bump on taxiway

Effective **OCTORBER 1, 2026**, to **OCTOBER 1, 2027,** taxiway F maintains a bump located 473M south of taxiway D, with the following coordinates 085759.48N 0793329.59W.
Caution.

REF AIP AD 2.2-6 (30 JUN 2018)
REF AIP AD 2.2-45 (30 SEP 2019)