**REPÚBLICA DE PANAMÁ**
**AUTORIDAD AERONÁUTICA CIVIL**
**DEPARTAMENTO INFORMACIÓN AERONÁUTICA**
***Sección de Publicaciones Aeronáuticas***

Direcciones:
AFS: MPLBYOYX
Comercial: AEROCIVIL Panamá
Tel.: (507) 520-1595 / 1596 / 1594
Fax: (507) NIL
e.mail: aispanama@aeronautica.gob.pa

Apartados 0816-03073 ó 0816-03187 Zona 5, Panamá

ó

Apartado 0843-02086 Balboa, Ancón

**SUP**

**A 21/26**

**01- Octubre- 2026**

# AD

## A-21/26 MARCOS A. GELABERT INTL AP (MPMG)

**Resalto en calle de rodaje**

A partir del **1 DE OCTUBRE DE 2026**, hasta el **1 DE OCTUBRE DE 2027**, la calle de rodaje G mantiene un resalto a 457.3M al sur de la calle de rodaje D localizado en la siguiente coordenadas 085759.18N 0793325.59W.
Tomar precauciones.

**REF AIP AD 2.2-6 (30 JUN 2018)**
**REF AIP AD 2.2-45 (30 SEP 2019)**

**REPUBLIC OF PANAMÁ**
**CIVIL AVIATION AUTHORITY**
**AERONAUTICAL INFORMATION DEPARTMENT**
*Aeronautical Publications Section*

Address: P.O. Box 0816-03073 ó 0816-03187
AFS: MPLBYOYX
Commercial: AEROCIVIL Panamá Zone 5, Panamá
Tel.: (507) 520-1595 / 1596 / 1594 ó
Fax: (507) NIL P.O. Box 0843-02086 Balboa, Ancón
e.mail: aispanama@aeronautica.gob.pa

**SUP**

**A21/26**

**October 1°, 2026**

# AD

## A-21/26 MARCOS A. GELABERT INTL AP (MPMG)
## Bump on taxiway

Effective **OCTORBER 1, 2026**, to **OCTOBER 1, 2027,** taxiway G maintains a bump located 457.3M south of taxiway D, with the following coordinates 085759.18N 0793325.59W.
Caution.

**REF AIP AD 2.2-6 (30 JUN 2018)**
**REF AIP AD 2.2-45 (30 SEP 2019)**