



REPÚBLICA DE PANAMÁ
AUTORIDAD AERONÁUTICA CIVIL
DEPARTAMENTO INFORMACIÓN AERONÁUTICA
Sección de Publicaciones Aeronáuticas

Direcciones:
AFS: MPLBYOXX
Comercial: AEROCIVIL Panamá
Tel.: (507) 520-1595 / 1596 / 1594 ó
Fax: (507) NIL
e.mail: aispanama@aeronautica.gob.pa

Apartados 0816-03073 ó
0816-03187
Zona 5, Panamá
Apartado 0843-02086
Balboa, Ancón

SUP

A13/26

1°- Junio- 2026

AD

A-13/26 PANAMA PACIFICO AP INTL (MPPA)
Luces fuera de servicio.

Hasta el **30 DE DICIEMBRE DE 2026**,
las luces de la calle de rodaje E y F
estarán fuera de servicio.
Las aeronaves deberán utilizar el
procedimiento FOLLOW ME.

ESTE SUPLEMENTO REEMPLAZA EL SUPLEMENTO A52/25



REPUBLIC OF PANAMÁ
CIVIL AVIATION AUTHORITY
AERONAUTICAL INFORMATION DEPARTMENT
Aeronautical Publications Section

Address: MPLBYOYX
AFS: MPLBYOYX
Commercial: AEROCIVIL Panamá
Tel.: (507) 520-1595 / 1596 / 1594 ó
Fax (507) NIL
e.mail: aispanama@aeronautica.gob.pa

P.O. Box 0816-03073 ó
0816-03187
Zone 5, Panamá
P.O. Box 0843-02086
Balboa, Ancón

SUP

A 13/26

June 1°, 2026

AD

A-13/26 PANAMÁ PACIFICO INTL AP (MPPA)
Lights out of service.

Until **DECEMBER 30, 2026**, the taxiway
Lights E and F will be out of service.
Aircraft must use the FOLLOW ME
procedure.

THIS SUPPLEMENT REPLACES SUPPLEMENT A52/25